



# SCA 3600

## SUPPORT CLEANING SYSTEM

### Optimized Performance with More Capabilities

Get versatility and efficient cleaning performance with the SCA 3600 support cleaning system. Built on the success of earlier models, the SCA 3600 is a larger and more capable system with a sleek, user-friendly design.

### Easy Support Removal

The SCA 3600 is a robust tool that dissolves support from 3D models created on any of the Stratasys 3D Printers that use Soluble Support Technology. It gently agitates 3D printed parts in a heated solution, effortlessly dissolving support material.



### SCA 3600 SUPPORT CLEANING SYSTEM

CLEAN, EFFICIENT SUPPORT  
REMOVAL PROCESS

CONVENIENT PRESET TEMPERATURES

USER-FRIENDLY DESIGN

INCREASED PART CAPACITY

LARGE DRAIN OUTLET AND QUICK  
DRAIN TIME

AVAILABLE STORAGE FOR DRAIN HOSE

SCREEN-PROTECTED DRAIN AND AGITATOR



# SCA 3600

## SUPPORT CLEANING SYSTEM

### PRODUCT SPECIFICATIONS

#### Physical Characteristics

Height – 1,086 mm (42.8 in)  
Width – 578 mm (22.8 in)  
Depth – 927 mm (36.5 in) incl. valve  
Weight (empty) – 73 kg (160.6 lbs)  
Weight (full) 171 kg (376 lbs)

#### Capacity

Tank – 102 L (27 gal)  
Large Basket – 406 x 406 x 356 mm  
(16 x 16 x 14 in)  
Small Basket – 100 x 100 x 100 mm  
(4 x 4 x 4 in)

#### Temperature Settings

50, 60, 70 and 85°C; +/- 2°C  
No-heat

#### Power Requirements

230 VAC +/- 10%, 50/60Hz, 15A  
Heater power - 3400 Watts max.

#### Regulatory Standards

CE/cTUVus

#### Cleaning Solutions

SCA 3600 uses WaterWorks® Soluble Concentrate or Ecoworks® to remove supports.

#### Safety Features

Over-temperature sensor  
Overfill/underfill sensor  
Auto-shutoff  
Heavy-duty locking casters

This versatile system offers temperature choices that readily clean supports from all the soluble support compatible materials. User-selectable temperature presets mean models are cleaned at the temperature optimal for soluble support materials. The ease of use continues with the built-in shelf for easy draining. Easily drain cleaning solution from clean parts by simply placing the basket on the built-in shelf while the cleaning solution drains from the basket and parts.

### MORE CAPACITY FOR MULTIPLE LARGE PARTS

The SCA 3600 is ideal for removing support material from large 3D printed models. Its sizable basket can hold parts up to 406 x 406 x 356 mm (16 x 16 x 14 in). That means it can clean a single large part, or multiple smaller parts in its roomy tank – saving time when multiple projects are in the queue.

The SCA 3600 includes a one-year limited warranty and comes with Stratasys' world-class global service and support network. Timely, onsite support is provided for the SCA 3600 by professionals trained to service 3D printing equipment.

**stratasys**

E info@stratasys.com / STRATASYS.COM  
ISO 9001:2008 Certified

#### HEADQUARTERS

7665 Commerce Way,  
Eden Prairie, MN 55344  
+1 800 801 6491 (US Toll Free)  
+1 952 937-3000 (Intl)  
+1 952 937-0070 (Fax)

2 Holtzman St., Science Park,  
PO Box 2496  
Rehovot 76124, Israel  
+972 74 745 4000  
+972 74 745 5000 (Fax)